

Good as New, Back to Work!

Situation

An explosion occurred at a California oilfield pumping station where the four pumps were fully immersed in a fire ball. All four pumps were disassembled to assess the extent of the damage. Several mechanical deficiencies were identified during the teardown inspection. The pumps were deemed repairable.

Solution

The pumps were obviously damaged from the explosion and fire but were also vintage and would need upgrades in monitoring and controls. Energy Link rebuilt the 4 pumps to OEM specifications and then put back into service.

The images below tell the story:

Extensive Fire Damage...



Mechanical Damage...



Resolution

Good as new and ready to get back to work:



**ENERGY
LINK** 
Your Service Connection™

11439 S. Enos Lane
Bakersfield, CA 93311
661-765-4444
EnergyLink1.com